


# SSCOM V5.10a Serial Debug Tool Instruction

SSCOM is a user-friendly serial debug software for multi-purposes. This instruction is to explain how to use the SSCOM tool to debug serial JPEG cameras.

**Step 1:** Download the software “SSCOM” from [www.jpegcamera.com](http://www.jpegcamera.com) website: Install it in your PC (supports windows only).

**Step 2:** Connect the camera to your PC through serial port, run SSCOM software, check the box says “English” shown as below, open the correct Com number that the camera is connected through. Choose the baud rate the same as the default baud rate of the camera that is connected.



For questions regarding this instruction, please email to [info@jpegcamera.com](mailto:info@jpegcamera.com)

**Step 3:** Check the box both for “SendHEX” and “HEXshow” first, then enter the command in the bottom box where it says “Type command here” and click “SEND”, the return (if there is any) will show up in the upper window of the application.

**Please note: when you type the command in the box, please make sure they are in HEX format, and leave one space between each two digits as shown below.**

